PM+_{Reserves®}

Veteran Owned Business

SPECIALIZING IN RESERVE STUDIES SINCE 1990

Cameron Station Community Association-FY24

PM+ Level III Updated Reserve Study Revision 1

Cameron Station Community Association C/o Mr. Steven P. Philbin, M ed., CMCA, ARM PCAM General Manager 200 Cameron Station Boulevard Alexandria, VA 22304

Dear Mr. Philbin:

Enclosed please find the revised Level III Updated Reserve Study (Financial Analysis Only) for Cameron Station Community Association. This is the Final Report, if there are questions or concerns please let us know. Also, please let us know if the cash on hand at the start of the fiscal year changes, we will issue a no cost change if it does.

Commonwealth of Virginia requirements for reserve studies are shown on page ii. Executive summary of study findings can be found on page 1.

For boards who need assistance in determining annual owner contribution for years between Level I and II studies, **PM+** is offering lower cost Level III reserve studies (financial reviews). Proposal provided upon request.

We thank the Board of Directors and CAMP Management for selecting PM+ for this study and hope you call upon us for your next study.

Sincerely,

-1.04

Mario B. "Ben" Ginnetti, PRA, RS, P.E. President

Enclosure: Study - PDF File





ommu



Alexandria. September 1,

PM+_{Reserves®}

Veteran Owned Business SPECIALIZING IN RESERVE STUDIES SINCE 1990

Cameron Station Community Association-FY24

PM+ Level III Updated Reserve Study Revision 1





September 1, 2023

Alexandria, VA



Prepared for:

Board of Directors



Mario B. "Ben" Ginnetti, PRA, RS, P.E.

© 2002-2023 by Mario B. Ginnetti This document contains copyright and proprietary data. It may only be reproduced for the exclusive use of Cameron Station Community Association. All other rights reserved by the author.

4388 Poplar Tree Court, Chantilly, VA 20151 000 703.803.8436

Cameron Station Community Association-FY24 Level III Revision 1

VIRGINIA REQUIREMENTS FOR RESERVE STUDIES	İİ
EXECUTIVE SUMMARY	1
READING AND UNDERSTANDING TABLES/CHARTS	3
APPENDIX A Documentation that supports the reserve contribution and other findings shown in the Executive Summary (page 1) begin on	1



VIRGINIA REQUIREMENTS FOR RESERVE STUDIES

§ 55.1- 1965 (Condo's) & 55.1-1826 (POA's), Annual budget; reserves for capital components (Enacted October 1, 2019)

- A. Except to the extent provided in the condominium instruments, the executive board shall, prior to the commencement of the fiscal year, make available to unit owners either (i) the annual budget of the unit owners' association or (ii) a summary of such annual budget.
- B. Except to the extent otherwise provided in the condominium instruments, the executive board shall:
 - 1. Conduct a study <u>at least once every five years</u> to determine the necessity and amount of reserves required to repair, replace, and restore the capital components as defined in § 55.1-1900;
 - 2. Review the results of that study at least annually to determine if reserves are sufficient; and
 - 3. Make any adjustments the executive board deems necessary to maintain reserves, as appropriate.
- C. To the extent that the reserve study conducted in accordance with this section indicates a need to budget for reserves, the unit owners' association budget shall include:
 - 1. The current estimated replacement cost, estimated remaining life, and estimated useful life of the capital components as defined in § 55.1-1900;
 - As of the <u>beginning of the fiscal year for which the budget is prepared, the current amount of accumulated cash reserves set aside to repair, replace, or restore the capital components and the amount of the expected contribution to the reserve fund for that fiscal year;
 </u>
 - 3. A <u>statement describing the procedures used for estimation and accumulation of cash reserves</u> pursuant to this section; and
 - 4. A <u>statement of the amount of reserves recommended in the study</u> and the <u>amount of current cash for</u> <u>replacement reserves.</u>

EXECUTIVE SUMMARY

KEY TO UNDERSTANDING STUDY RESULTS – Purpose of a reserve study is to establish a financial plan for keeping the property's common and limited common elements in good repair. The plan is developed by identifying the component, assessing its condition, and estimating both the time when work will be needed and cost of work. In a **PM+** study these entries can be found beginning on page A1, columns (1), (4) and (5). Those entries combined with reserve savings, current reserve contribution, interest, and inflation rates and how much of a contingency should be preserved to fund unforeseen events are the factors that determine the reserve contribution.

RELEVANT DATA

1st Study Year FY24
FY Begins 1-Jan-24\$395,010 Contribution FY23
2.47% InflationInspection Date(s) NA
Units 1,7690.00% Interest

<u>Accumulated Cash at Start of FY (COH)</u> and Current Year Contribution were provided to PM+ and were best estimates available when provided, they are not audited amounts.

INTEREST AND INFLATION¹ rates best project future property needs. Inflation is based on the last 10-year Consumer Price Index (CPI) average; interest on savings is not applied to the reserves at his property. Even at relatively low levels, inflation is a primary driver for the contribution and has a large impact over the period of the study. If inflation increases at a materially higher rate than indicated, the study should be updated more frequently to maintain adequate reserves and avoid large future assessment increases.

STUDY SUMMARY	Cash Flow
Reserve Contribution Recommended for FY24	\$424,470
Accumulated Cash on Hand (COH) Start of FY24	1,367,500
Current Estimated Replacement Cost	5,591,060
Average Useful Life Years (All Components) ²	23.6
Average Remaining Life Years (All Components) ²	7.2
Additional Study Values	
Average Yearly Owner Contribution	240
30 Year Income	22,733,070
30 Year Income From Interest	0
30 Year Income From Assessments	22,733,070
Years 1-30 Minimum Threshold \$ ³	474,590
%	8.5%
Years 31-50 Minimum Threshold \$ 3	359,530
%	6.4%

OUR ANALYSIS, based on study assumptions, indicates the association will need to:

- Contribute the highlighted (Cash Flow) amount in FY24 to meet the reserve needs of the property.
- The recommended FY24 amount will need to be increased, year over year, through FY27, by 7.5% to build up the reserves to pay for future work. (Note to avoid significant annual increases in the contribution, between study updates, keep the yearly contribution adjusted for inflation).

^{1.} Although factors used may not prove to be precise they should be reasonable predictors of future costs and return on savings.

^{2.} See columns (3) & (4) starting on Page A1 for average and remaining useful life of each component.


^{3.} Minimum Threshold - 30 and 50 years shown. If 50-year is high at this time, it will adjust with future updates.

• For projections of the **Cash Flow** contributions needed, over life of this study, see 30 & 50-Year Financial Plan tables in appendix A, column (14), and column (15) for contributions and year end year end balances the contributions should provide. If the **Component** method is used to fund the reserves see same financial plan tables, columns (17) and (18), for yearly contributions and year end balances.

OBJECTIVE OF THE ANNUAL CONTRIBUTION: 1) funds should always be available to pay for needed work, 2) preserve a minimum threshold for contingencies, and 3) long range projections of expenses and contributions should not show a need for special assessments or loans. To achieve those objectives, **PM+** studies consider the first thirty-years and an additional twenty-years, making the "look at" period a total of 50-years. This projection assures the recommended contribution is based on a sound long-range analysis of the property's reserve needs. Contributions in future studies will vary with accrued savings, useful lives, inflation, interest, and cost for work.

FOR VIRGINIA PROPERTIES – Information the executive board is to make available to unit owners, prior to commencement of the fiscal year, is listed in Study Summary. For statement required PM suggest: "The association expected contribution to the reserves in FY _____ will be \$_____. Procedures the association uses for estimation and accumulation of cash reserves was provided by an independent reserve study professional."

<u>RECOMMENDATION</u> - Fund the reserves to the recommended amount using the Cash Flow method. Failure to fund could be a violation of State Statute, where enacted, that requires funding to the reserve study recommendation, and/or, result in insufficient funds to pay for work. Insufficient funds can result in a special assessment, a loan or significant future increase in annual contribution to build up the reserves to where they should be – any of these can place financial hardships on owners. Least cost option to owners is to fund the recommendation.



WHERE CONTRIBUTIONS TO THE RESERVES GO OVER 30-YEARS:

READING and UNDERSTANDING TABLES/CHARTS

(Some information may not appear in this study).

RELEVANT DATA

Study fiscal year, inspection date(s), number of homes, association's financial data, and interest/inflation rates.

SUMMARY OF THE ASSOCIATION'S RESERVE FINANCIAL PLAN

Financial summary of study results.

TABLE OF REPAIR & REPLACEMENT RESERVES

The Repair and Replacement Table shows the common and/or limited common elements, average and remaining useful life, and estimated cost for work (actual cost can vary from estimated based on many factors). This information, for the most part, is self-explanatory; however, when we believe more information is needed, we provide comments or use photographs.

Column

- (1) The property components the association should include in the reserves. Where a 15%, 30%, etc., is shown it means total replacement of the item is not anticipated. If we have omitted or added components that are not common or limited common area responsibility, please inform us so we can provide a revised table. It also applies if the association accomplishes the work from their annual operating expense and a reserve set-aside is not needed. If components are included that are operating expenses, we leave it to others to determine the correct tax consequence of the component.
- (2) Approximate quantity and unit of measure. The following abbreviations are used; however, they may not all appear in this study:

AC – Acres	LF - Linear Feet	SY - Square Yards
AnAvg - Annual Average	LS - Lump Sum	TN - Tons
BLD - Building	HP - Horsepower	UN - Units
EA - Each	RC - Replacement Cost	> - Greater Than
CY - Cubic Yards	SF - Square Feet	< - Less Than

- (3) The components' average useful life (Avg). Leading publications on useful life data, our own experiences and historical trends are used to determine average useful life.
- (4) Our best estimate of the remaining useful life (RUL). Some components in the table may not fail precisely as shown. We use the remaining useful life in conjunction with the estimated cost to calculate the annual contribution needed to fund the component. Actual remaining useful life can be significantly different.
- (5) Estimated costs are in current dollars. Estimates are based on similar work in the greater Washington area, association experience, industry publications, such as R.S. Means and HomeTech, contractors and other reliable sources. It assumes the association will competitively seek bids and obtain a fair price in today's market. Some work, such as balconies, roofing, garages, façade, boilers, utility systems ,chiller replacements, etc., may need the services of an engineer or architect to determine scope and oversee repairs. Those estimates take precedence over those shown in the table. Some costs can be more predictable than others, i.e., when roofs and pavements are replaced the entire component will most likely be replaced total replacement cost is used. Other components, i.e., closed loop piping, plumbing, electrical and fire protection systems may not need total replacement and will continue to perform with spot repairs. For these components, we reserve a reasonable amount for this work.
- (6) Distribution of the funds the association had (is projected to have) at the start of their fiscal year or the amount we were requested to use. The program distributes a prorated amount to each component.

Cameron Station Community Association-FY24 Level III Revision 1

- (7) The amount needed to fund the balance of the requirement.
- (8) The contribution needed to fund the 1st year applying the cash flow method. Contributions from year to year are mainly adjustments for inflation.
- (9) The contribution needed to fund the 1st year applying the component method. Contributions from year to year can vary significantly.

30 and 50-Year Comparison of Financial Plans

Column

- (10) Fiscal Year.
- (11) Projected annual expenses.
- (12) Cumulative expenses over 30-years.
- (13) and (16) Interest earned per funding plan based on previous year-end balance.
- (14) and (17) Contribution needed per funding plan.
- (15) and (18) Projected year-end balance per funding plan.

GRAPHS

Graphs depict the projected contributions and year end balances for each plan. The contribution objective should be to have a consistent contribution, year after year, which can be maintained with inflation adjustments. Avoid fluctuating contributions as they can impose financial hardships on owners. The plot objective for the reserve balance is to have the year end balances always above the "X" axis. If it falls below, it indicates a special assessment or loan will be needed to support the reserves.

SUMMARY

- 30-Year Income projected from interest and owners.
- 30 & 50-Year Minimum/Maximum Balances includes contingency for unforeseen events.

PROPERTY COMPARISON

The "Property Comparison" chart compares the property's current funding to the last 100 properties we have studied. The comparison shows the maximums, minimums, property averages and medians compared to your property. Property features differ from one property to another so consider these as averages only and not a true comparison on your property to another similar property. Four comparisons are made:

- % Funded Ratio of the <u>current</u> to the <u>ideal</u> Reserve Balance for each component in the Reserve Table. The ratio is a product of the "used-up" life, useful life, and component cost.
- Reserve Depletion Factor Number of years amount-on-hand will fund (It is the same as the "go broke" date if no more money is added to the reserves).
- Accumulated cash at start of fiscal year dedicated reserve funds the association had or is estimated to have when their fiscal year begins.
- Average annual contribution per owner Average contribution per owner needed to meet the reserve requirement. Dollar amounts will vary from property to property based on construction features, common/limited common elements, past contributions to the reserves and other factors that may not result in a true comparison.

APPENDIX A

Reserve S	Study
-----------	-------

COMPONENT					STIMATED I		BALANCE	FY24 CONTRIBUT	1011										
	QUA	NTITY	AVG R		COST IN CURRENT \$	OF COH AS OF 1-Jan-24	NEEDED TO FUND RESERVE	CONTRIBUT CASH FLOW CO METHOD	MPONENT	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033
(1)	(2)		(3)	(4)	(5)	(6)	(7)	(8)	(9)										
COMMUNITY CENTER EXTERIOR																			
ROOFING-SHINGLES	7,869	SF	20	2	43,280	10,590	32,690	4,600	16,350	0	44,350	0	0	0	0	0	0	0	0
ROOFING-METAL	92	SF		22	4,160	1,020	3,140	40	140	0	0	0 0	0	0	0 0	0	0	0	0
ROOFING FLAT	1,800	SF	20	3	41,390	10,120	31,270	2,940	10,420	Ő	0 0	43,460	0	0	0	0	0	0	Ő
GUTTERS/DOWNSPOUTS FAÇADE	875	LF	30	6	13,130	3,210	9,920	470	1,650	0	0	0	0	0	14,830	0	0	0	0
FACADE/CAULK/WATERPROOFING		LS	5	1	6,060	1,480	4,580	1,290	4,580	6,060	0	0	0	0	6,850	0	0	0	0
PAINT/DETERIORATED WOOD REPLACEMENT WINDOWS/DOORS/HARDWARE		LS	6	1	13,560	3,320	10,240	2,880	10,240	13,560	0	0	0	0	0	15,700	0	0	0
BUILDING EXTERIOR DOORS	9	EA	25	3	38,650	9,450	29,200	2,740	9,730	0	0	40,580	0	0	0	0	0	0	0
WINDOWS	69	EA		18	74,070	18,120	55,950	880	3,110	0 0	Ő	0	0	0	0	0	0	0	0 0
LOGO ENTRY MATS	1	EA	6	5	34,650	8,480	26,170	1,470	5,230	0 0	Ő	0	0	38,200	0	0	0	0	0 0
NEW HANDICAP/ADA DOORS	4	EA		18	16,400	4,010	12,390	190	690	0 0	Ő	0 0	0	00,200	0	0	0	0	0 0
MISC. DOOR REPLACEMENT INTERIOR DECORATION AND FEATURES		LS	10	5	4,500	1,100	3,400	190	680	0	0	0	0	4,960	0	0	0	0	0
FLOORING-CARPET (INCLUDES STAIRWAYS)	598	SY	8	1	39,880	9,750	30,130	8,480	30,130	39,880	0	0	0	0	0	0	0	48,480	0
STAIRWAY (RUBBER TILE)	380	SF	20	9	3,420	840	2,580	80	290	0	0	0	0	0	0	0	0	4,160	0
CEILING TILE-FOYER CLOSET	39	SF	30	1	390	100	290	80	290	390	0	0	0	0	0	0	0	0	0
FURNISHINGS/TV'S		LS	15	4	35,350	8,650	26,700	1,880	6,680	0	0	0	38,030	0	0	0	0	0	0
CEILING LIGHTING FIXTURES		LS	30	8	19,610	4,800	14,810	520	1,850	0	0	0	0	0	0	0	23,260	0	0
PAINT COMMON AREAS		LS	7	6	27,000	6,600	20,400	960	3,400	0	0	0	0	0	30,500	0	0	0	0
INTERIOR DOOR REPLACEMENTS MANAGEMENT OFFICE EQUIPMENT		LS	5	1	3,000	730	2,270	640	2,270	3,000	0	0	0	0	3,390	0	0	0	0
DESK & CHAIR	8	LS	15	4	11,200	2,740	8,460	600	2,120	0	0	0	12,050	0	0	0	0	0	0
COMPUTERS & PERIPHERALS	8	LS	5	1	21,600	5,280	16,320	4,600	16,320	21,600	0	0	0	0	24,400	0	0	0	0
TABLES/CHAIRS/TELEPHONE/MISCELLANEOUS		LS	20	4	38,000	9,290	28,710	2,020	7,180	0	0	0	40,890	0	0	0	0	0	0
BATHROOM RENOVATION		LS	15	6	9,000	2,200	6,800	320	1,130	0	0	0	0	0	10,170	0	0	0	0
LIGHTING TO LED CLUBHOUSE & HALLWAYS		LS	30	29	26,800	6,560	20,240	200	700	0	0	0	0	0	0	0	0	0	0
DESK/EQUIPMENT KITCHEN		LS	15	4	4,300	1,050	3,250	230	810	0	0	0	4,630	0	0	0	0	0	0
RENOVATION FITNESS ROOM		LS	15	6	20,000	4,890	15,110	710	2,520	0	0	0	0	0	22,600	0	0	0	0
PELOTON	2	EA	4	4	5,800	1,420	4,380	310	1,100	0	0	0	6,240	0	0	0	6,880	0	0
EXERCISE EQUIPMENT	10	EA	9	1	30,000	7,340	22,660	6,380	22,660	30,000	0	0	0	0	0	0	0	0	37,370
EXERCISE EQUIPMENT	9	EA	9	2	30,000	7,340	22,660	3,190	11,330	0	30,740	0	0	0	0	0	0	0	0
EXERCISE EQUIPMENT	10	EA	9	3	30,000	7,340	22,660	2,130	7,550	0	0	31,500	0	0	0	0	0	0	0
EXERCISE EQUIPMENT	9	EA	9	4	30,000	7,340	22,660	1,600	5,670	0	0	0	32,280	0	0	0	0	0	0
EXERCISE EQUIPMENT	10	EA	9	5	30,000	7,340	22,660	1,280	4,530	0	0	0	0	33,080	0	0	0	0	0
EXERCISE EQUIPMENT	2	EA	9	7	30,000	7,340	22,660	910	3,240	0	0	0	0	0	0	34,730	0	0	0
RUBBER FLOOR TILES	2,900	EA	8	6	32,000	7,830	24,170	1,130	4,030	0	0	0	0	0	36,150	0	0	0	0
LIGHTING TO LED		LS	30	29	12,000	2,940	9,060	90	310	0	0	0	0	0	0	0	0	0	0
BASKETBALL COURT																			
REPLACE FLOOR		LS	40	18	44,910	10,980	33,930	530	1,890	0	0	0	0	0	0	0	0	0	0
LIGHTING TO LED	1	LS	30	29	2,000	490	1,510	10	50	0	0	0	0	0	0	0	0	0	0
BASKETBALL STANDARD Mechanical/plumbing/electrical systems	1	EA	30		5,000	1,220	3,780	60	210	0	0	0	0	0	0	0	0	0	0
MECHANICAL BOILER-DOMESTIC HOT WATER	1,260	MBU	20		50,400	12,330	38,070	5,360	19,040	0	51,640	0	0	0	0	0		0	0
HOT WATER STORAGE TANK	1	EA	30	28	5,000	1,220	3,780	40	140	0	0	0	0	0	0	0	0	0	0
HVAC	20	TN		1	68,000	16,630	51,370	14,470	51,370	68,000	0	0	0	0	0	0	0	0	0
	20	TN		5	68,000	16,630	51,370	2,890	10,270	0	0	0	0	74,970	0	0	0	0	0
HVAC	20	111					01,070	2,000	10,2701	0	0	0	0	14,310	0				

COMPONENT					ESTIMATED		BALANCE	FY24											
	QUA	NTITY			COST IN CURRENT \$	OF COH AS OF 1-Jan-24	NEEDED TO FUND RESERVE	CONTRIBU CASH FLOW (METHO	COMPONENT	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033
(1)	(2)		(3)	(4)	(5)	(6)	(7)	(8)	(9)										
EXHAUST FANS-1/2		LS	15	1	3,000	730	2,270	640	2,270	3,000	0	0	0	0	0	0	0	0	0
EXHAUST FANS-1/2		LS	15	3	3,000	730	2,270	210	760	0	0	3,150	0	0	0	0	0	0	0
PLUMBING																			
PLUMBING/SANITARY/CONDENSATE PIPE ELECTRICAL		LS	50	28	43,000	10,520	32,480	330	1,160	0	0	0	0	0	0	0	0	0	0
ELECTRICAL SYSTEMS		LS	40		40,000	9,780	30,220	470	1,680	0	0	0	0	0	0	0	0	0	0
CARRIAGE LIGHTS AT DOORS	11	EA	30	8	3,580	880	2,700	100	340	0	0	0	0	0	0	0	4,250	0	0
BATTERY BACKUP/EXIT LIGHT FIXTURES FIRE PROTECTION/SECURITY	40	EA	15	1	10,000	2,450	7,550	2,130	7,550	10,000	0	0	0	0	0	0	0	0	0
FIRE ALARM SYSTEM REPAIRS		LS	40		72,200	17,660	54,540	850	3,030	0	0	0	0	0	0	0	0	0	0
FIRE SPRINKLER SYSTEM REPAIRS		LS	10		19,950	4,880	15,070	850	3,010	0	0	0	0	22,000	0	0	0	0	0
ACCESS SECURITY SYSTEM		LS	15		57,000	13,940	43,060	930	3,310	0	0	0	0	0	0	0	0	0	0
		LS	10	8	14,000	3,420	10,580	370	1,320	0	0	0	0	0	0	0	16,610	0	0
FIRE HYDRANT PAINTING		LS	6	5	5,570	1,360	4,210	240	840	0	0	0	0	6,140	0	0	0	0	0
FIRE HYDRANT PAINTING		LS	6		5,570	1,360	4,210	200	700	2 500	0 3 500	0	0	0	6,290	0	0	4 250	0
FIRE HYDRANT SERVICING MISC. MECHANICAL/PLUMBING/ELECTRICAL/FIRE		LS LS	1	1	3,500	860	2,640	740	2,640 3,970	3,500 5,250	3,590 0	3,680 0	3,770 5,650	3,860 0	3,950 0	4,050 6,080	4,150 0	4,250 0	4,360 6,540
ELEVATOR		L5	3	I	5,250	1,280	3,970	1,120	3,970	5,250	0	0	0,000	0	0	0,000	0	0	0,040
ELEVATOR/CAB-HYDRAULIC	1	EA	25	3	200,000	48,920	151,080	14,180	50,360	0	0	210,000	0	0	0	0	0	0	0
MEN'S & LADIES LOCKER ROOMS																			
RENOVATION	2	EA	15		142,000	34,730	107,270	2,320	8,250	0	0	0	0	0	0	0	0	0	
LOCKERS	84	EA	15		10,080	2,470	7,610	430	1,520	0	0	0	0	11,110	0	0	0	0	
FLOOR MATS	1,194	SF	15	5	11,940	2,920	9,020	510	1,800	0	0	0	0	13,160	0	0	0	0	0
	0.747	05	-		04 700	0.050	40.070	5 000	10.070	04 700	0	•	0	•	07.000	•	0	•	0
	2,747 288	SF SF	5 5		24,720	6,050	18,670	5,260	18,670	24,720	0 0	0	0	0	27,930	0	0	0	0
WHITECOAT-WADING POOL FILTER/PUMPS/PIPING/CHEMICAL EQUIPMENT	200	LS	5 10		3,740 16,000	910 3,910	2,830 12,090	800 1,130	2,830 4,030	3,740 0	0	0 16,800	0	0	4,230 0	0	0	0	0
COPING/TILES/WALLS & GENERAL REPAIRS		LS	10		37,730	9,230	28,500	1,610	4,030	0	0	10,000	0	41,600	0	0	0	0	0
POOL DECK/COPING & TILE-PRIOR TO POOL OPEN		LS	10	1	3,910	960	2,950	830	2,950	3,910	4,010	4,110	4,210	4,310	4,420	4,530	4,640	4,750	-
POOL FURNITURE		LS	8	2	56,270	13,760	42,510	5,990	21,260	0,510	57,660	4,110 0	4,210	4,010	-,-20	4,000	4,040 0	4,700 0	
UMBRELLAS		LS	8	4	54,240	13,270	40,970	2,880	10,240	0	0	0 0	58,360	0	0	0	0	0	0
SHADE AWNING		LS	10	6	3,400	830	2,570	120	430	0	0	0	0	0	3,840	0	0	0	0
REPLACE CONCRETE DECK	6,865	SF	50	28	130,440	31,900	98,540	990	3,520	0	0	0	0	0	0	0	0	0	0
6' METAL FENCE	295	LF	30	8	32,450	7,940	24,510	860	3,060	0	0	0	0	0	0	0	38,490	0	0
3' METAL FENCE	80	LF	30	8	6,800	1,660	5,140	180	640	0	0	0	0	0	0	0	8,070	0	0
ADULT POOL COVER	2,747	SF	10		12,360	3,020	9,340	330	1,170	0	0	0	0	0	0	0	14,660	0	0
WADING POOL COVER	288	SF	10	1	3,310	810	2,500	700	2,500	3,310	0	0	0	0	0	0	0	0	0
TOTAL BUILDING(S)					2,159,520	528,200	1,631,320	129,360	459,340										
PAVEMENTS/CONCRETE																			
PAVEMENTS																			
PREVENTIVE MAINTENANCE	22,069	SY	4		50,760	12,420	38,340	5,400	19,170	0	52,010	0	0	0	57,350	0	0	0	63,230
	22,069	SY	15		408,280	99,860	308,420	6,680	23,720	0	0	0	0	0	0	0	0	0	-
BASE/SUB-BASE/REPAIRS	1,103	SY	15		32,000	7,830	24,170	520	1,860	0	0	0	0	0	0	0	0	0	0
	24 754	LS SY	15 4		35,050	8,570	26,480	570	2,040	0	0	0	0	0	0	0 92,530	0	0	0
PREVENTIVE MAINTENANCE PAVEMENT OVERLAY	34,754 34,754	SY	4 15		79,930 660,330	19,550 161,510	60,380 498,820	5,670 10,030	20,130 35,630	0	0	83,930 0	0	0	0	92,530	0	0	0
BASE/SUB-BASE/REPAIRS	1,738	SY	15		50,390	12,330	490,020	770	2,720	0	0	0	0	0	0	0	0	0	0
CONSULTANT	1,750	LS	15		56,730	13,880	42,850	860	3,060	0	0	0	0	0	0	0	0	0	0
PREVENTIVE MAINTENANCE	34,754	SY	4		79,930	19,550	60,380	17,000	60,380	0	0	0	0	88,120	0	0	0	97,160	0
PAVEMENT OVERLAY	34,754	SY	15		660,330	161,510	498,820	140,470	498,820	660,330	0	0	0	00,120	0	0	0	07,100	-
BASE/SUB-BASE/REPAIRS	1,738	SY	15		50,390	12,330	38,060	10,720	38,060	50,390	0	0	0	ů 0	Ő	0	0	0	ů 0
CONSULTANT	.,	LS	15		56,730	13,880	42,850	12,070	42,850	56,730	0	0	0	Ő	Ő	ů 0	0	Ő	Ő
ANNUAL REPAIR COSTS (POTHOLES, ETC)		LS	1		7,000	1,710	5,290	1,490	5,290		7,170		7,530	7,720	7,910	8,100	8,300	8,510	8,720
				-	.,	.,	-,	.,	-,	.,	,	,,	,	,0	,	.,	.,	.,	

COMPONENT					ESTIMATED I		BALANCE	FY24											
	QUA	NTITY	AVG R (YRS		COST IN CURRENT \$	OF COH AS OF	NEEDED TO FUND RESERVE	CONTRIBUT	OMPONENT	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033
(1)	(2)		(3)	(4)	(5)	1-Jan-24 (6)	RESERVE (7)	METHOD (8)	S (9)										
CONCRETE/PAVERS																			
SIDEWALKS-BRICK PAVERS		LS	1	1	27,000	6,600	20,400	5,740	20,400	27,000	27,670	28,350	29,050	29,770	30,500	31,260	32,030	32,820	33,630
CURBS/GUTTERS OTHER CONCRETE		LS	4	1	18,630	4,560	14,070	3,960	14,070	0	19,090	0	0	0	21,050	0	0	0	23,210
CONSULTANT ASPHALT		LS	15	13	28,250	6,910	21,340	460	1,640	0	28,950	0	0	0	31,920	0	0	0	35,190
485910-796320-832800		20	10	10						0	20,000	0	0	0	01,520	Ū	0	Ū	00,100
TOTAL PAVEMENTS/CONCRETE					2,301,730	563,000	1,738,730	222,410	789,840										
OTHER PROPERTY FEATURES																			
ENTRANCE FEATURE WALLS/SIGNAGE		LS	5	2	1,600	390	1,210	170	610	0	1,640	0	0	0	0	1,850	0	0	0
TREES/SHRUBBERY-DISEASED/DEAD		LS	1	1	31,000	7,580	23,420	6,600	23,420	31,000	31,770	32,550	33,350	34,180	35,020	35,890	36,770	37,680	38,610
PROPERTY LINE FENCE BETWEEN COMERCIAL STORES	2,990	LF	20	18	180,000	44,030	135,970	2,130	7,550	0	0	0	0	0	0	0	0	0	0
PROPERTY LINE FENCE-REPAIRS & SEAL COAT	5,980	SF	6	4	20,930	5,120	15,810	1,110	3,950	0	0	0	22,520	0	0	0	0	0	26,070
FENCE CONSULTANT		LS		18	6,500	1,590	4,910	80	270	0	0	0	0	0	0	0	0	0	0
DUKE STREET COLUMNS/FENCE REPAIRS PAINT GAZEBOS/ARBORS	100	LF	6	1	3,390	830	2,560	720	2,560	3,390	0	0	0	0	0	3,920	0	0	0
CAMERON STATION BOULEVARD GAZEBO	4 000	05	00	40	07.000	0 750	00.050	070	4 000	0	0	0	0	•	0	0	•	0	0
ROOFING	1,200	SF		16	27,600	6,750	20,850	370	1,300	0	0	0	0	0	0	0	0	0	0
RAILING PAINT/STAINING/STRUCTURAL REPAIRS	100	SF LS	30 6	8 1	6,000 3,900	1,470 950	4,530 2,950	160 830	570 2,950	0 3,900	0 0	0 0	0	0 0	0	0 4,510	7,120 0	0 0	0 0
JOHN TICER DRIVE GABEZO ROOFING	166	SF		16	5,480	1,340	4,140	70	2,950	3,900	0	0	0	0	0	4,510	0	0	0
PAINT/STAINING/STRUCTURAL REPAIRS	100	LS	6	10	2,800	680	2,120	600	2,120	2,800	0	0	0	0	0	3,240	0	0	0
DONOVAN DRIVE ARBOR		10	0	1	2,000	000	2,120	000	2,120	2,000	0	0	0	0	0	5,240	0	0	0
STRUCTURE REPAIRS	1,000	SF	40	18	38,000	9,290	28,710	450	1,600	0	0	0	0	0	0	0	0	0	0
DONOVAN DRIVE FOUNTAIN																			
WATERPROOF BASIN		LS	8	2	2,700	660	2,040	290	1,020	0	2,770	0	0	0	0	0	0	0	3,360
PUMP/PIPINGGENERAL REPAIRS		LS	10	3	1,100	270	830	80	280	0	0	1,160	0	0	0	0	0	0	0
LANDSCAPE ENHANCEMENTS SITE LIGHTING		LS	20	19	27,000	6,600	20,400	300	1,070	0	0	0	0	0	0	0	0	0	0
STREET LIGHT RETROFIT TO LED		LS	NA	1	40,000	9,780	30,220	8,510	30,220	40,000	0	0	0	0	0	0	0	0	0
STREET LIGHT RETROFIT TO LED		LS	NA	2	40,000	9,780	30,220	4,250	15,110	0	40,990	0	0	0	0	0	0	0	0
STREET LIGHT RETROFIT TO LED		LS	NA	3	40,000	9,780	30,220	2,840	10,070	0	0	42,000	0	0	0	0	0	0	0
STREET LIGHT RETROFIT TO LED		LS	NA	4	40,000	9,780	30,220	2,130	7,560	0	0	0	43,040	0	0	0	0	0	0
STREET LIGHT RETROFIT TO LED		LS	NA	5	40,000	9,780	30,220	1,700	6,040	0	0	0	0	44,100	0	0	0	0	0
STREET LIGHT RETROFIT TO LED		LS	NA	6	40,000	9,780	30,220	1,420	5,040	0	0	0	0	0	45,190	0	0	0	0
STREET LIGHT RETROFIT TO LED		LS	NA	7	40,000	9,780	30,220	1,220	4,320	0	0	0	0	0	0	46,310	0	0	0
STREET LIGHT RETROFIT TO LED		LS	NA	8	40,000	9,780	30,220	1,060	3,780	0	0	0	0	0	0	0	47,450	0	0
STREET LIGHT RETROFIT TO LED		LS	NA	9	40,000	9,780	30,220	950	3,360	0	0	0	0	0	0	0	0	48,620	0
STREET LIGHT RETROFIT TO LED		LS	NA	10	40,000	9,780	30,220	850	3,020	0	0	0	0	0	0	0	0	0	49,820
TABLES/BENCHES/GRILLS//TRASH/DOGGIE POSTS		1.0	00	40	2 700	000	0.000	40	400	0	0	•	0	•	0	0	•	0	0
BEASLEY POCKET PARK FURNITURE		LS		18 1	3,700	900	2,800	40	160	0	0	0	0	0	0	0	0	0	0
PARK BENCHES REPAIRS PARK BENCHES REPAIRS		LS LS	40 40	2	8,500 8,500	2,080 2,080	6,420 6,420	1,810 900	6,420 3,210	8,500 0	8,710	0	0	0	0	0	0	0	0
PARK BENCHES REPAIRS		LS	40	2	8,500	2,080	6,420	600	2,140	0	0,710	8,930	0	0	0	0	0	0	0
PARK BENCHES REPAIRS		LS	40	4	8,500	2,000	6,420	450	1,610	0	0	0,350	9,150	0	0	0	0	0	0
PARK BENCHES REPAIRS		LS	40	5	8,500	2,080	6,420	360	1,280	0	0	0	0,100	9,370	0	0	0	0	0
PARK BENCHES REPAIRS		LS	40	6	8,500	2,080	6,420	300	1,070	0	ů 0	0	0	0,010	9,600	Ŭ	Ő	0	0
PARK BENCHES REPAIRS		LS	40	7	8,500	2,080	6,420	260	920	0	ů 0	0	0	0 0	0,000	9,840	Ő	0	0
PARK BENCHES REPAIRS		LS	40	8	8,500	2,080	6,420	230	800	0	ů 0	0	0	0 0	0	0,010	-	0	0
PARK BENCHES REPAIRS		LS	40	9	8,500	2,080	6,420	200	710	0	0 0	0	0	Ő	0	0	0	10,330	0
PARK BENCHES REPAIRS		LS		10	8,500	2,080	6,420	180	640	0	ů 0	0	0	0	Ũ	Ŭ	Ő	0	10,590
PARK BENCHES REPAIRS		LS		11	8,100	1,980	6,120	160	560	0	0	0	0	0	Ő	n	ů 0	0 0	0,000
PARK BENCH REPLACEMENT	73	EA		20	103,440	25,300	78,140	1,100	3,910	0	0	0	0	0	0	0	0	0	0
	40	EA	15	6	21,000	5,140	15,860	740	2,640	0	ů 0	ů 0	0 0	Ő	23,720	0	0 0	0 0	0

COMPONENT	APPR QUA	OX'MT NTITY	USEFUL I AVG I (YR	REM	STIMATED COST IN CURRENT \$	DISTR'BTN OF COH AS OF 1-Jan-24	BALANCE NEEDED TO FUND RESERVE	FY24 CONTRIBU CASH FLOW METHO	JTION COMPONENT	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033
(1)	(2)		(3)	(4)	(5)	(6)	(7)	(8)	(9)										
DOGGIE STATIONS PARTIAL REPLACEMENT	7	EA	10	2	3,420	840	2,580	360	1,290	0	3,500	0	0	0	0	0	0	0	0
DOGGIE STATIONS PARTIAL REPLACEMENT	7	EA	10	4	3,250	790	2,460	170	620	0	0	0	3,500	0	0	0	0	0	0
DOGGIE STATIONS PARTIAL REPLACEMENT STORM WATER FACILITIES	7	EA	10	6	3,100	760	2,340	110	390	0	0	0	0	0	3,500	0	0	0	0
STORM WATER RUN OFF SANITARY SEWER SYSTEM		LS	1	1	20,000	4,890	15,110	4,250	15,110	20,000	20,490	21,000	21,520	22,050	22,600	23,150	23,730	24,310	24,910
AS NEEDED REPAIRS OTHER SITE FEATURES		LS	3	2	18,000	4,400	13,600	1,910	6,800	0	18,440	0	0	19,850	0	0	21,350	0	0
IRRIGATION SYSTEM UPKEEP		LS	1	1	8,000	1,960	6,040	1,700	6,040	8,000	8,200	8,400	8,610	8,820	9,040	9,260	9,490	9,720	9,960
SITE ITEMS VEHICLE		LS	1	1	2,800	680	2,120	600	2,120	2,800	2,870	2,940	3,010	3,090	3,160	3,240	3,320	3,400	3,490
GOLF CART REPLACEMENT		LS	10	7	12,000	2,940	9,060	360	1,290	0	0	0	0	0	0	13,890	0	0	0
TOTAL OTHER PROPERTY FEATURES					1,049,810	256,730	793,080	55,680	197,780										
CAPITAL IMPROVEMENTS EV CHARGING STATIONS		LS	10	1	80.000	19,570	60,430	17,020	60,430	80,000	0	0	0	0	0	0	0	0	0
		20		·						00,000	•	· ·	°,	•	· ·	Ŭ	•	· ·	v
					80,000	19,570	60,430	17,020	60,430										
TOTAL RESERVES					\$5,591,060	\$1,367,500	\$4,223,560	\$424,470	\$1,507,390	\$1,241,760	\$466,260	\$589,890	\$387,390	\$520,460	\$500,110	\$352,080	\$320,650	\$334,190	\$454,020
					======	======	======	======	======	======	======	=====	======	=====	=====	======	======	=====	======

Notes:

All dollars rounded to nearest \$10. Totals may not add due to rounding.

One year remaining useful life indicates component useful life is used up.

Cameron Station Community Association-FY24 Revision 1

USEFUL LIFE ESTIMATED

COST IN

YEARS 11-30 EXPENSES

AVG REM CURRENT \$ (YRS) (1) (3) (4) (5) COMMUNITY CENTER EXTERIOR ROOFING-SHINGLES 43,280 72,250 ROOFING-METAL 4.160 6,940 ROOFING FLAT 41 390 70.800 GUTTERS/DOWNSPOUTS 13.130 FAÇADE FACADE/CAULK/WATERPROOFING 6,060 7,730 8,740 9,870 11,150 EXTERIOR PAINTING PAINT/DETERIORATED WOOD REPLACEMENT 13.560 18.170 21.040 24.350 WINDOWS/DOORS/HARDWARE BUILDING EXTERIOR DOORS 38,650 74,690 74.070 112,150 WINDOWS LOGO ENTRY MATS 34.650 44.230 51.200 59.270 68.610 NEW HANDICAP/ADA DOORS 16,400 24,830 MISC. DOOR REPLACEMENT 4,500 6,330 8,080 INTERIOR DECORATION AND FEATURES 58.930 FLOORING-CARPET (INCLUDES STAIRWAYS) 39 880 71 630 STAIRWAY (RUBBER TILE) 3,420 6,770 CEILING TILE-FOYER CLOSET FURNISHINGS/TV'S 35,350 54 840 CEILING LIGHTING FIXTURES 19.610 PAINT COMMON AREAS 27.000 36.180 42.920 50.920 INTERIOR DOOR REPLACEMENTS 3,000 3,830 4,330 4,890 5,520 MANAGEMENT OFFICE EQUIPMEN DESK & CHAIR 11 200 17 380 31.150 **COMPUTERS & PERIPHERALS** 21.600 27.570 35.190 39.750 TABLES/CHAIRS/TELEPHONE/MISCELLANEOUS 38,000 66,610 BATHROOM RENOVATION 9,000 14,660 53,070 LIGHTING TO LED CLUBHOUSE & HALLWAYS 26,800 CONCIERGE DESK/EQUIPMENT 4,300 6,670 KITCHEN 32.580 RENOVATION 20,000 FITNESS ROOM PELOTON 5,800 7,590 8,360 ,170 11,210 9.220 EXERCISE EQUIPMENT 30,000 ,540 57,970 EXERCISE EQUIPMENT 30,000 38,290 ,690 59,410 EXERCISE EQUIPMENT - 3 30.000 39 240 48 870 60.870 EXERCISE EQUIPMENT 30,000 40,210 50,080 41,200 EXERCISE EQUIPMENT 30,000 51,320 EXERCISE EQUIPMENT 30,000 43,260 53,880 32 000 43 940 53.420 64.930 RUBBER FLOOR TILES LIGHTING TO LED 12,000 23,760 BASKETBALL COURT REPLACE FLOOR 44.910 68.000 LIGHTING TO LED 2,000 3,960 BASKETBALL STANDARD 5.000 7.570 MECHANICAL/PLUMBING/ELECTRICAL SYSTEMS MECHANICAL 50,400 84.130 BOILER-DOMESTIC HOT WATER HOT WATER STORAGE TANK 5.000 9.660 HVAC 68,000 98.050 HVAC 68,000 HVAC 102,000 136,700 197,110 **EXHAUST FANS-1/2** 4 3 3 0 3 000 EXHAUST FANS-1/2 3,000 4,540 PLUMBING PLUMBING/SANITARY/CONDENSATE PIPE 43,000 83,100 ELECTRICAL ELECTRICAL SYSTEMS 40.000 60.560 3,580 CARRIAGE LIGHTS AT DOORS BATTERY BACKUP/EXIT LIGHT FIXTURES 10,000 14,420

FIRE PROTECTION/SECURITY

COMPONENT

YEARS 11-30 EXPENSES

Cameron Station Community Association-FY24 Revision 1

COMPONENT		E ESTIMATED																				
	AVG REM (YRS)	COST IN CURRENT \$	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053
(1)	(3) (4) (5)																				
FIRE ALARM SYSTEM REPAIRS FIRE SPRINKLER SYSTEM REPAIRS ACCESS SECURITY SYSTEM FIRE HYDRANT REPLACEMENT FIRE HYDRANT PAINTING FIRE HYDRANT PAINTING FIRE HYDRANT SERVICING MISC. MECHANICAL/PLUMBING/ELECTRICAL/FIRE	40 18 10 9 15 13 10 6 6 9 6 0 1 7 3 7	5 19,950 3 57,000 3 14,000 5 5,570	0 0 0 7,110 0 4,470 0	0 0 0 0 7,280 4,580 0	0 076,390 0 0 4,690 7,040	0 0 0 0 0 4,810 0	0 28,070 0 0 0 4,930 0	0 0 0 0 5,050 7,570	0 0 0 8,230 0 5,170 0	109,320 0 21,200 0 8,430 5,300 0	0 0 0 0 5,430 8,150	0 0 0 0 5,560 0	0 0 0 0 5,700 0	0 0 0 0 5,840 8,760	0 0 9,530 0 5,990 0	0 0 0 9,760 6,130 0	0 35,830 0 0 0 0 6,290 9,430	0 0 0 0 6,440 0	0 0 0 0 6,600 0	0 0 110,150 27,050 0 0 6,760 10,150	0 0 0 11,030 0 6,930 0	0 0 0 11,300 7,100 0
ELEVATOR ELEVATOR/CAB-HYDRAULIC	25	3 200,000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	386,490	0	0
MEN'S & LADIES LOCKER ROOMS RENOVATION LOCKERS FLOOR MATS POOL(S)	15 13 15 4 15 4	5 10,080	0 0 0	0 0 0	190,300 0 0	0 0 0	0 0 0	0 0 0	0 0 0	0 0 0	0 0 0	0 16,030 18,980	0 0 0	0 0 0	0 0 0	0 0 0	0 0 0	0 0 0	0 0 0	274,410 0 0	0 0 0	0 0 0
WHITECOAT-ADULT POOL WHITECOAT-WADING POOL FILTER/PUMPS/PIPING/CHEMICAL EQUIPMENT COPING/TILES/WALLS & GENERAL REPAIRS POOL DECK/COPING & TILE-PRIOR TO POOL OPEN POOL FURNITURE UMBRELLAS SHADE AWNING REPLACE CONCRETE DECK 6' METAL FENCE 3' METAL FENCE ADULT POOL COVER WADING POOL COVER	5 5 10 1 1 8 8 4 10 50 21 30 4 30 4 10 4 10	3 16,000 5 37,730 1 3,910 2 56,270 4 54,240 5 3,400 8 32,450 8 6,800 3 12,360 1 3,310	31,550 4,770 0 4,990 0 0 0 0 0 0 0 0 0 4,220	0 0 5,110 0 70,940 0 0 0 0 0 0 0 0 0 0 0	0 021,440 05,240 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 5,370 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 53,090 5,500 0 0 0 0 0 0 0 0 0 0 0 0 0	35,650 5,390 0 5,640 0 4,900 0 0 0 0 0 0 0 0 0 0 0 0	0 0 5,780 0 0 0 0 0 0 0 0 0 0 0 0	0 0 5,920 85,200 0 0 0 0 0 18,710 0	0 0 6,070 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 6,220 0 86,230 0 0 0 0 0 0 0 0 0 0	40,270 6,090 0 6,370 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 6,530 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 27,370 0 6,690 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 6,850 0 0 0 0 0 0 0 0 0 0 0 0	0 0 67,770 7,020 0 0 0 0 0 0 0 0 0 0 0 0 0 0	45,500 6,880 0 7,200 103,560 0 6,260 0 0 0 0 0 0 0 0 0 0 0	0 0 7,370 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 7,560 0 104,820 0 252,070 0 23,890 0	0 0 7,740 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 7,930 0 0 0 0 0 0 0 0 0 0 0 0
TOTAL BUILDING(S)		2,159,520																				
PAVEMENTS/CONCRETE PAVEMENTS PREVENTIVE MAINTENANCE PAVEMENT OVERLAY BASE/SUB-BASE/REPAIRS CONSULTANT PREVENTIVE MAINTENANCE PAVEMENT OVERLAY BASE/SUB-BASE/REPAIRS CONSULTANT PREVENTIVE MAINTENANCE PAVEMENT OVERLAY BASE/SUB-BASE/REPAIRS CONSULTANT ANNUAL REPAIR COSTS (POTHOLES,ETC) CONCRETE/PAVERS	4 15 11 15 11 15 11 15 11 15 14 15 14 15 14 15 14 15 15 15 15 15 1	3 408,280 3 32,000 3 35,050 3 79,930 4 660,330 4 56,730 1 79,930 1 56,730 1 56,730 1 7,000	0 0 102,020 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0 9,160	0 547,170 42,890 46,970 0 0 0 107,120 0 0 0 9,380	0 0 996,810 69,200 77,910 0 0 0 9,610	0 0 0 0 0 0 0 0 0 0 0 0 9,850	0 0 0 0 0 952,160 72,660 81,800 10,090	75,000 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 121,020 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 127,070 0 0 0 11,130	82,690 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 11,400	0 0 0 133,430 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 140,100 0 140,200 0 12,270	91,170 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 147,110 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0 0 13,200	0 788,990 61,840 67,730 0 0 0 154,460 0 0 13,530	0 0 0 1,307,580 99,780 0 112,340 0 0 0 13,860	0 0 0 0 0 0 0 0 0 0 0 0 14,200
SIDEWALKS-BRICK PAVERS CURBS/GUTTERS OTHER CONCRETE	1 4	1 27,000 1 18,630	34,460 0	35,310 0	36,180 24,970	37,080 0	37,990 0	38,930 0	39,890 27,530	40,880 0	41,890 0	42,920 0	43,980 30,350	45,070 0	46,180 0	47,320 0	48,490 33,460	49,690 0	50,920 0	52,180 36,000	53,470 0	54,790 0
CONSULTANT ASPHALT 485910-796320-832800 TOTAL PAVEMENTS/CONCRETE	15 13	3 28,250 2,301,730	0	0	37,860	0	0	0	41,740	0	0	0	46,020	0	0	0	50,740	0	0	54,590	0	0
OTHER PROPERTY FEATURES ENTRANCE FEATURE WALLS/SIGNAGE TREES/SHRUBBERY-DISEASED/DEAD PROPERTY LINE FENCE BETWEEN COMERCIAL STORES PROPERTY LINE FENCE-REPAIRS & SEAL COAT FENCE CONSULTANT DUKE STREET COLUMNS/FENCE REPAIRS PAINT GAZEBOS/ARBORS CAMERON STATION BOULEVARD GAZEBO ROOFING	5 2 1 20 14 6 4 20 14 6 7 38 16	1 31,000 8 180,000 4 20,930 8 6,500 1 3,390	0 39,570 0 0 0 0	2,090 40,540 0 0 0 0	0 41,550 0 0 4,540	0 42,570 0 0 0 0	0 43,620 0 0 0 0	0 44,700 0 30,180 0 0 39,800	2,360 45,800 0 0 0 0	0 46,940 272,530 0 9,840 0	0 48,100 0 0 5,260	0 49,280 0 0 0 0	0 50,500 0 0 0 0	2,670 51,750 0 34,940 0 0	0 53,030 0 0 0 0	0 54,340 0 0 0 0	0 55,680 0 0 6,090	0 57,050 0 0 0 0	3,020 58,460 0 0 0 0	0 59,910 0 40,450 0 0	0 61,390 0 0 0 0	0 62,900 0 0 0 0

YEARS 11-30 EXPENSES

Cameron Station Community Association-FY24 Revision 1

COMPONENT			ESTIMATED																				
	AVG RI (YRS		COST IN CURRENT \$	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053
(1)	(3)	(4)	(5)																				
RAILING	30	8	6,000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
PAINT/STAINING/STRUCTURAL REPAIRS	6	1	3,900	Ő	Ő	5,230	Ő		Ő	Ő	Ő	6,050	Ő	Ő	Ő	Ő	Ő	7,000	Ő	Ő	Ő	Ő	Ő
JOHN TICER DRIVE GABEZO																							
ROOFING	38	16	5,480	0	0	0	0	0	7,900	0	0	0	0	0	0	0	0	0	0		0	0	0
PAINT/STAINING/STRUCTURAL REPAIRS DONOVAN DRIVE ARBOR	6	1	2,800	0	0	3,750	0	0	0	0	0	4,340	0	0	0	0	0	5,030	0	0	0	0	0
STRUCTURE REPAIRS	40	18	38,000	0	0	0	0	0	0	0	57.530	0	0	0	0	0	0	0	0	0	0	0	0
DONOVAN DRIVE FOUNTAIN	10		00,000	Ŭ	°,	Ŭ	•	Ŭ	•	Ŭ	01,000	Ŭ	· ·		· ·		•	Ū	°,	°,	°,	· ·	Ŭ
WATERPROOF BASIN	8	2	2,700	0	0	0	0	0	0	0	4,090	0	0	0	0	0	0	0	4,970	0	0	0	0
PUMP/PIPINGGENERAL REPAIRS	10	3	1,100	0	0	1,470	0		0	0	0	0	0	0	0	1,880	0	0	0	0	0	0	0
LANDSCAPE ENHANCEMENTS	20	19	27,000	0	0	0	0	0	0	0	0	41,890	0	0	0	0	0	0	0	0	0	0	0
SITE LIGHTING STREET LIGHT RETROFIT TO LED	NA	1	40,000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
STREET LIGHT RETROFIT TO LED	NA	2	40,000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
STREET LIGHT RETROFIT TO LED	NA	3	40,000	0	ů 0	ů 0	0	Ő	0	Ő	0	0	0	0 0	0	0 0	0	0	0 0	ů 0	0	0	ů 0
STREET LIGHT RETROFIT TO LED	NA	4	40,000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
STREET LIGHT RETROFIT TO LED	NA	5	40,000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
STREET LIGHT RETROFIT TO LED	NA	6	40,000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
STREET LIGHT RETROFIT TO LED STREET LIGHT RETROFIT TO LED	NA NA	7 8	40,000 40,000	0	0	0	0	0 0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0 0
STREET LIGHT RETROFIT TO LED	NA	о 9	40,000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
STREET LIGHT RETROFIT TO LED	NA	10	40,000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
TABLES/BENCHES/GRILLS//TRASH/DOGGIE POSTS			,																				
BEASLEY POCKET PARK FURNITURE	20	18	3,700	0	0	0	0	0	0	0	5,600	0	0	0	0	0	0	0	0	0	0	0	0
PARK BENCHES REPAIRS	40	1	8,500	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
PARK BENCHES REPAIRS	40	2	8,500	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
PARK BENCHES REPAIRS PARK BENCHES REPAIRS	40 40	3 4	8,500 8,500	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0 0
PARK BENCHES REPAIRS	40 40	4 5	8,500	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
PARK BENCHES REPAIRS	40	6	8,500	0	0	Ő	0	0	0	0	0	Ő	0	0	0	0	0	0	0	0	0	0	Ő
PARK BENCHES REPAIRS	40	7	8,500	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
PARK BENCHES REPAIRS	40	8	8,500	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
PARK BENCHES REPAIRS	40	9	8,500	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
PARK BENCHES REPAIRS PARK BENCHES REPAIRS	40 40	10 11	8,500 8,100	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
PARK BENCHES REPAIRS PARK BENCH REPLACEMENT	40 20	20	0,100 103,440	10,340 0	0	0	0	0	0	0	0	0	164,450	0	0	0	0	0	0	0	0	0	0
METAL TRASH CONTAINER	15	6	21,000	0	0	0	0	0	0	0	0	0	0,450	34,210	0	0	0	0	0	0	0	0	0
DOGGIE STATIONS PARTIAL REPLACEMENT	10	2	3,420	0	4,470	0	0	0	0	0	0	0	0	0	5,710	0	0	0	0	0	0	0	0
DOGGIE STATIONS PARTIAL REPLACEMENT	10	4	3,250	0	0	0	4,460	0	0	0	0	0	0	0	0	0	5,700	0	0	0	0	0	0
DOGGIE STATIONS PARTIAL REPLACEMENT	10	6	3,100	0	0	0	0	0	4,470	0	0	0	0	0	0	0	0	0	5,710	0	0	0	0
STORM WATER FACILITIES			00.000	05 500	00.400	00.000	07.170	00.440	00.040	00 550	00.000	04.000	04.000	00 500		04.040	05 000	05 000	00.040	07 700	00.050		40 500
STORM WATER RUN OFF SANITARY SEWER SYSTEM	1	1	20,000	25,530	26,160	26,800	27,470	28,140	28,840	29,550	30,280	31,030	31,800	32,580	33,390	34,210	35,060	35,920	36,810	37,720	38,650	39,600	40,580
AS NEEDED REPAIRS	3	2	18,000	22,970	0	0	24,720	0	0	26,600	0	0	28,620	0	0	30,790	0	0	33,130	0	0	35,640	0
OTHER SITE FEATURES	0	-	.0,000	22,010	°,	Ŭ	21,720	Ŭ	•	20,000	· ·	Ŭ	20,020		· ·	00,100	•	Ū	00,100	°,		00,010	Ŭ
IRRIGATION SYSTEM UPKEEP	1	1	8,000	10,210	10,460	10,720	10,990		11,540	11,820	12,110	12,410	12,720	13,030	13,350	13,680	14,020	14,370	14,720	15,090	15,460	15,840	16,230
SITE ITEMS	1	1	2,800	3,570	3,660	3,750	3,850	3,940	4,040	4,140	4,240	4,340	4,450	4,560	4,670	4,790	4,910	5,030	5,150	5,280	5,410	5,540	5,680
VEHICLE GOLF CART REPLACEMENT	10	7	12,000	0	0	0	0	0	0	17,730	0	0	0	0	0	0	0	0	0	22,630	0	0	0
TOTAL OTHER PROPERTY FEATURES			1,049,810																				
CAPITAL IMPROVEMENTS																							
EV CHARGING STATIONS	10	1	80,000	102,110	0	0	0	0	0	0	0	0	0	130,320	0	0	0	0	0	0	0	0	0
			80,000																				
TOTAL RESERVES			\$5.591.060	\$538,470	\$266,590	\$1,486,710	\$1.309.990	\$232,720	\$1,603,950	\$461.810	\$1,147,390	\$372.290	\$813,400	\$689,520	\$624,620	\$427,500	\$413.240	\$649.830	\$599,480	\$271.210	\$3.026.290	\$1.986.320	\$346.510
					,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	,010	,,020		,,=10	,,,	,100	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

2036

2036

2039

2042

2045

----Component Method Funding

2048

2051

2039


2042

2045

Component Method Funding

2048

2051



Notes:

* An annual average cost. Expenditures can change from year-to-year depending on when actual work is done.


Contribution and projections are based on the study fiscal year and will change if estimated cost, useful life, amount-on-hand, contribution and contingency to be preserved change.

Data should be considered a more accurate projection for years 1 - 5 than the out-years.

Minimum balance does not include the first year.

If component method calculations are included note how column (17) contributions vary from one year to the next.


A highlighted cell in column (14) indicates future contributions from that year on will vary from past contributions, either due to inflation or work accomplished.



50 YEAR FINANCIAL PLAN(S)

COMPARISON TO OTHER PROPERTIES Sample Size = 100 HOA's/POA'S





Legend:

This comparison only compares the first study year to other properties.

% Funded -- Used-up life divided by Useful Life times Current Cost.

Reserve Depletion Factor -- Number of years the amount-on-hand will fund if no more is contributed to the reserves.

AOH - Reserve funds available at start of fiscal year.

Cost Per Owner - The average cost per owner to meet the reserve requirement compared to other properties.